

#### Manufacturer:



Terazidere Mah.60.Yil Cad.No:5/3 34035 Bayrampasa/ISTANBUL/TURKEY

TEL: 0 212 501 48 63 FAX: 0 212 501 48 83



# **MODEL OP-LP1 MODEL OP-LP2**

**POSITION MEASUREMENT** AND CONTROL DEVICE

# Ver 2.0E **USER GUIDE**



# WARNING!

# **READ CAREFULLY BEFORE POWER ON**

- Complete electrical connections according to the schematic at the last page.
- Check Supply Voltage 220V AC, or DC, due to Specifications on the equipment.
- Use only shielded cable for sensors.
- Keep away the equipment from direct heat source.
- MODEL OP-LP1 and MODEL OP-LP2 is not suitable for outdoor use.
- Keep away the equipment from water or other liquid drains.
- Do not open, modify or replace any component in the equipment, If any problem occurs please contact an authorised **OPKON** technical service or **OPKON** directly.

# **ELECTRICAL SPECIFICATIONS:**

Microcontroller based 12 bit Analog/Digital converter Offset calibration Screen filter Hysteresis Rs485 serial communication

Power Supply Power Consumption Transducer supply voltage Transducer supply current

Relays max. ratings

1xNO+NC 8A,230V AC :Relav1 1xNO+NC 8A,230V AC Relay2

Relay3 1xNO+NC 8A,230V AC :0 - 5VDC

:<4 VA(protected by fuse 50mA)

:+5V or +12VDC(selectable by jumper)

:220V ± % 20 .50 Hz

:Max.100mA(no fuse)

Output Suply voltage Input Voltage :0 - 5VDC Input

:Potentiometric (Resistive potentiometer> 50 ohm.) or 0-5V input

**MECHANICAL SPECIFICATIONS:** 


**Dimensions** :48x96x128 mm (LP1), 96x48x128 mm (LP2) Panel cut dimensions

:45x90 mm (LP1), 90x45 mm (LP2)


:ABS plastic Body :0-60 °C Working temperature Storage temperature :-10°C ...+80°C

# **DESCRIPTIONS**


MODEL OP-LP1 (VERTICAL)



MODELOP-LP2 (HORIZONTAL)



PROCESS DISPLAY



MENU AND PARAMETER DISPLAY

OUT3



**BUTTONS** 

LED INDICATORS

Enters to Set Parameter menu.
Saves the values.
Turns on When programming.

Enters to Device Parameter menu.

CAL

Changes the values down.

Changes the values up. Used to adjust Offset.

Turns on While device is running.


PRG
CAL Turns on When Calibrating the device.

ERR Turns on an error occured.

OUT1
Turns on When Relay1 is activated.

OUT2
Turns on When Relay2 is activated.

Turns on When Relay3 is activated.



CAL DER DUTL DUTE DUTS

CAL

CAL

mm.

mm.

Flt Parameter is used to Fitler the vibrations coming from a system Which is the Transducer connected .



-<u>Press</u> UP/DOWN buttos to write FLt value on display. -<u>Press</u> PRG to save and pass next Parameter.

Fn Parameter is used to choose Offset Function active or passive.Pls refer to page of "OFFSET ADJUSTMENT"

- **0** Offset Function is *passive*.
- 1 Offset Function is active.



- -Press UP/DOWN buttos to write Fn value on display.
- -<u>Press</u> PRG to save and pass next Parameter.

Adr Parameter is used to define an adress to device when running in a Network.



-<u>Press</u> UP/DOWN buttos to write Adr value on display. <u>-Press</u> PRG to save.Parameter.


Thus the Device Parameter settings were completed. Device turns back run mode automatically.


#### DEVICE PARAMETER MENU

In MODEL OP-LP1 and MODEL OP-LP2 devices 4 Parameters HYS ,FLt ,Fn and Adr are available by user to adjust the device.

**HYS**: Hysteresis Parameter. **FIt**: Fitler Parameter.

Fn : Offset Function Parameter .
Adr : Network Adress Parameter.
Setting these Parameters is shown below.






HYS Parameter is used to tolerate the values of Relays will be not activated. Relays not active at **SET values –(minus) HYS value** 



- -Press UP/DOWN buttos to write HYS value on display.
- -Press PRG to save and pass next Parameter

#### CALIBRATION

At first power on Device must be calibrated. Every device must be calibrated according to used resistive transducer CALIBRATION is shown below



# CAL screen is definning the Lower Calibration Point screen.

Move the sensor to the *designated* as *minimum* position mechanicaly.

- Press PRG button.
- Device will designate Zero for this position automatically.

# CAH screen is definning the Upper Calibration Point screen.


Move the sensor to the designated as maximum position mechanicaly.


- Press UP/DOWN buttons to write Upper Calibration Point value on the display.
- Press PRG button.

Thus the *calibration was completed*. Device turns back run mode automatically.

#### SET PARAMETER MENU

In Set Parameter Menu 3 Parameters **St1**, **St2** and **St3** are available. These Parameters indicate the value of **Relay1**, **Relay2** and **Relay3** will be pulled. Adjusting the Parameters is shown below.






# While the device is running;

- Press PRG button to enter menu..
- Press UP/DOWN buttons to write St1 value.
- Press PRG button.
- Press UP/DOWN buttons to write St2 value.
- Press PRG button.
- Press UP/DOWN buttons to write St3 value.
- Press PRG button.

Thus the Parameters was adjusted. Device turns back run mode automatically.

# **OFFSET ADJUSTMENT**

Offset Adjustment is used to define the position of transducer as **zero** or any other designated position.Offset Adjustment is done as shown below.



# While the device is running;

Move the transducer to any position designated as offset point mechanically.

- Press UP button.
- **Press UP/DOWN** buttons to write zero or any value to offset the position of transducer.
- Press PRG buton.

Thus the Offset Adjustment was completed. Device turns back run mode automatically.